

# Direct Forklift and Equipment

7885 Southern Blvd, Boardman OH 44512

[www.directforklift.com](http://www.directforklift.com)

330.726.4050

BM8530

Type of Equipment	Side Loader
Make	Baumann

Model	GX70/16/40ST
Serial Number	8530

Year	2014
Hours	9053



Capacity	15000
Tire Type	Pneumatic
Fuel	DIESEL
Hydraulic Controls	Finger Tip
Hydraulic Functions	Three
Mast Height Lowered	120
Max Lift Height	157.5
Free Lift	Yes
Mast Stage	Two
Fork Length	63
Drive Tire Size	32x12.1-15
Steer Tire Size	32x12.1-15
Attachments	
Key Included?	Yes
Weight	26235

Fork Condition	Good
Upright Condition	Good
Lift Cylinder Condition	Good
Hydraulics Condition	Good
Carriage Condition	Good
Drive Axle Condition	Good
Brakes Condition	Good
Parking Brake Condition	Good
Shift Action Condition	Good
Steer Axle Condition	Good
Sheet Metal Condition	Good
Drive Tire Condition	Worn
Drive Tire Tread	50%
Steer Tire Condition	Worn
Steer Tire Tread	50%
Electrical System Condition	Good
Seat Condition	Torn
Lights Condition	Good
Engine Condition	Good
Cooling System Condition	Good

Unit Operating?	Yes
Overall Rating	Fair
Overall Appearance	Good

Engine Info	VM R754EU5
-------------	------------

### Shipping dimensions in inches (")

Length	204	Add fork length or attachment dimensions when applicable
Width	102	
Height	124	

BM8530

Comments

Engine hard starting; needs further diag.  
 Ignition switch going bad; needs replaced.  
 Engine shuts down after aprox 5 mins with no operator in seat;  
 possible timer setting.  
 Warning light comes on and drive will lock out if ladder is not in fully  
 raised position.  
 Engine oil was low and fluid dark; added 1.5 qts oil.  
 Dry res around engine oil filter & mount on block.  
 Engine cover latch non operational.  
 Added 2 qts coolant to reservoir.  
 Moist res on trans/hydro pump assy.  
 Dry residue on crankcase breather.  
 Wet oil dripping off of valve bodies/junctions & hoses on bottom of  
 hyd pump assys; mild.  
 Dry res on all three ground control lever assys.  
 Very early signs of steer cylinder seeping.  
 Mild play in steer pins & bushings.  
 HVAC fan intermittently noisy; operates all speeds.  
 L running light non operational.  
 Cab door sticky/dragging in channels; needs diag.  
 Front WS washer not spraying. Fluid is getting to sprayer; nozzle  
 may be blocked. R sprayer operates; nozzle needs redirected.  
 Primary air filter dirty; blown out needs replaced.

Missing: (1) finger tip toggle switch cover, dash plug or gauge, (1) air  
 box lid clip, front and/or L tow pin, carriage camera (mount is  
 present), ground control metal cover latch, ops manual, optional  
 stereo & speakers and/or CB radio.  
 Damaged: Floor mat, (1) finger tip toggle switch cover, air box lid,  
 serpentine belt, cab strobe light, spotlight, top cab worklight, (3) tire  
 press rings dent/bent, R rear lower metal mild dents/bends, both R  
 side platform's wood & latches, L front tow pin mount bent, metal  
 ground control cover, metal crossbar @bottom of mast bent, L cab  
 grab bar & mount, front treadboard dent/bent, R platform prop arm  
 bent, seat belt latch bent.  
 Needs Adj: Lift chains.



Type	001 70/10/200 ST	
Ser.No.	8530	
Year	2014	
Rating kg	7000	
Load center mm	800	
Net weight kg	11900	
Attachments kg	450	
Batt. weight kg	100	
Gross weight kg (A+B+C)	12750	
Front axle max capacity kg	11000	
Rear axle max capacity kg	11000	
Power Rating kW		