

Direct Forklift and Equipment

7885 Southern Blvd, Boardman OH 44512

www.directforklift.com

330.726.4050

CL0138

Type of Equipment	Standard Forklift
Make	Clark

Model	GEX40
Serial Number	GEX450-0138-9868KF

Year	2014
Hours	5966



Unit Operating?	Yes
Overall Rating	Fair
Overall Appearance	Good

Capacity	8000
Tire Type	Pneumatic
Fuel	ELECTRIC
Hydraulic Controls	Finger Tip
Hydraulic Functions	Four
Mast Height Lowered	103
Max Lift Height	216
Free Lift	Yes
Mast Stage	Three
Fork Length	
Drive Tire Size	250x15 -7.50
Steer Tire Size	21x8x9 - 6.00
Attachments	
Key Included?	No
Weight	12550
Battery Included	Yes
Battery Voltage	80

Fork Condition	
Upright Condition	Good
Lift Cylinder Condition	Good
Hydraulics Condition	Good
Carriage Condition	Good
Drive Axle Condition	Good
Brakes Condition	Low Pedal
Parking Brake Condition	Good
Shift Action Condition	Good
Steer Axle Condition	Good
Sheet Metal Condition	Good
Drive Tire Condition	Good
Drive Tire Tread	90%
Steer Tire Condition	Good
Steer Tire Tread	80%
Electrical System Condition	Good
Seat Condition	Good
Lights Condition	Good

Drive Motor	Good
Hydraulic Pump Motor	Good
Pwr Strg Motor	Good

Shipping dimensions in inches (")

Length	124	Add fork length or attachment dimensions when applicable
Width	54.5	
Height	102	

Battery compartment dimensions (")

Length	39.25
Width	40.5
Height	30.25

CL0138

Comments

Data plate is not riveted to hood; serial# matches number stamped in frame.
Unit needs RFID key to turn on, no key provided at delivery: physical ignition does nothing.
Service brake has soft/low brake pedal, needs diag; added brake fluid to reservoir.
St/cyl L side has early signs of seeping; no leaks.
Dry oily res bottom of orbitrol & hoses; no drips.
Dry residue on skid plate; mild.
Tilt cyl has small divot in chrome ram; not leaking.
Hydraulics have delay when released; functions continue to operate for brief second.
Rear WS wiper motor not wired in.
Front defroster is non operational.
Heater on floorboard is non operational.
Hyd pump has mild noise.
Steer pins/bshgs have very mild play.
Last service listed 7-3-17 @5343 hrs.

Missing: (1) rubber plug/cover for optional hood mounted hyd levers, both cab doors, both WS wiper assy, rear defroster switch, hood latch post, R plastic seat back hinge cover.
Damaged: Rear window defroster, R front worklight mount/guard, front WS wiper motor cover cracked, fire extinguisher damaged on base, floor mat cut/ worn.
Needs Adj: Lift chains.

