

Direct Forklift and Equipment

7885 Southern Blvd, Boardman OH 44512

www.directforklift.com

330.726.4050

CL0139

Type of Equipment	Standard Forklift
Make	Clark

Model	GEX40
Serial Number	GEX450-0139-9868KF

Year	2014
Hours	6680



Unit Operating?	Yes
Overall Rating	Fair
Overall Appearance	Good

Capacity	8000
Tire Type	Pneumatic
Fuel	ELECTRIC
Hydraulic Controls	Finger Tip
Hydraulic Functions	Four
Mast Height Lowered	103
Max Lift Height	216
Free Lift	Yes
Mast Stage	Three
Fork Length	
Drive Tire Size	250-15 -7.50
Steer Tire Size	21X8X9 6.00
Attachments	
Key Included?	No
Weight	12550
Battery Included	Yes
Battery Voltage	80

Fork Condition	
Upright Condition	Good
Lift Cylinder Condition	Good
Hydraulics Condition	Good
Carriage Condition	Good
Drive Axle Condition	Noisy
Brakes Condition	Good
Parking Brake Condition	Good
Shift Action Condition	Good
Steer Axle Condition	Good
Sheet Metal Condition	Good
Drive Tire Condition	Good
Drive Tire Tread	80%
Steer Tire Condition	Worn
Steer Tire Tread	55%
Electrical System Condition	Good
Seat Condition	Good
Lights Condition	Good

Drive Motor	Noisy
Hydraulic Pump Motor	Good
Pwr Strg Motor	Good

Shipping dimensions in inches (")

Length	124	Add fork length or attachment dimensions when applicable
Width	54.5	
Height	102	

Battery compartment dimensions (")

Length	
Width	
Height	

CL0139

Comments

Unit needs RFID card to turn on; no key provided at delivery.
 Wet oily res on front part of skid plate; mild drips.
 Wet oily res on a orbitrol hose & fitting.
 Wet dripping oil from main hyd hose return T fitting
 Wet oily dripping res bottom of hyd control block.
 Dry residue on R tread board and down side.
 Unit has loud whirr & whine noise from drive motors/ final drive.
 Brake pedal is low/ soft; brakes are working and will lock up.
 Reservoir half full; no fluid added.
 Hydraulics have delay when released; functions continue to operate for brief second.
 Floor mounted heater non operational.
 BU alarm sounds in both fwd/rev.
 Strobe is non operational.
 Floor board horn switch non operational.
 Horn works but is weak.
 Male DC adaptor not mounted to lift.
 Front window defroster fan is operating but heat does not work.
 Rear defrost switch operates; is not wired in to window due to damaged glass.
 Carriage has mild play.
 Mild play in steer pins & bushings.
 Tires are solid pneumatics.
 Last service listed 11-1-17 @ 5315 hrs.

Missing: Both cab doors, both WS wiper arm assy, (1) rubber plug/cover for optional hood hyd control, front window defroster hand bolt, steer tire press rings & locks, hood latch post.
 Damaged: Rear window defroster, R battery gate bent/dents, R rear lower metal OHG cover, R front worklight guard/mount bent, hood cracked, R plastic seat back hinge cover, rubber floormat cut/torn, seat adj rails sticky.
 Needs Adj: Lift chains, tilt sync.

