

Direct Forklift and Equipment

7885 Southern Blvd, Boardman OH 44512

www.directforklift.com

330.726.4050

CL2162

Type of Equipment	Standard Forklift
Make	Clark

Model	GEX25
Serial Number	GEX230-2162-965KF

Year	
Hours	



Unit Operating?	Yes
Overall Rating	Fair
Overall Appearance	Good

Capacity	5000
Tire Type	Pneumatic
Fuel	ELECTRIC
Hydraulic Controls	Finger Tip
Hydraulic Functions	Four
Mast Height Lowered	85.5
Max Lift Height	189
Free Lift	Yes
Mast Stage	Three
Fork Length	
Drive Tire Size	23x9-10
Steer Tire Size	18x7-8
Attachments	
Key Included?	No
Weight	6597
Battery Included	Yes
Battery Voltage	80

Fork Condition	
Upright Condition	Good
Lift Cylinder Condition	Good
Hydraulics Condition	Needs Attention
Carriage Condition	Good
Drive Axle Condition	Good
Brakes Condition	Good
Parking Brake Condition	Good
Shift Action Condition	Good
Steer Axle Condition	Good
Sheet Metal Condition	Good
Drive Tire Condition	Good
Drive Tire Tread	80%
Steer Tire Condition	Good
Steer Tire Tread	75%
Electrical System Condition	Needs Work
Seat Condition	Good
Lights Condition	Good

Drive Motor	Good
Hydraulic Pump Motor	Good
Pwr Strg Motor	Good

Shipping dimensions in inches (")

Length	101.25	Add fork length or attachment dimensions when applicable
Width	47	
Height	87	

Battery compartment dimensions (")

Length	27.5
Width	40.25
Height	30.5

CL2162

Comments

Unit ignition is RFID Key.
Lift keeps shutting itself down whether operating or not; needs further diag.
Unable to drive unit far and/or fast enough before it shuts down to fully test all functions; at short distance drive line, motors, hyd & steer pumps all sound good. Brake pedal feels good.
Unable to check all electrical functions before unit shuts down.
Fourth function hydraulics non oper; need diag.
Hyd oil in tank below dipstick; none added.
Both steer w/brgs need inspected, lube & adjusted.
Multi tiny knicks in free lift cyl chrome; no leaks.
BU alarm sounds in both directions.
Brake fluid 1/3 full; fluid clean none added.
Top OHG glass has been replaced with plexiglass, not sealed or secured.
Front windshield is plexiglass & installed poorly.
Last repair shown 8-24-17 @5896 hrs.

Missing: Both L cab doors, R front cab door, R metal side cover hand bolt, both R side cover grommets, R rearview mirror, L side cover & hdw, both WS wiper arm assys, (1) rubber optional hood hyd lever plug, steer tire press rings & locks, cab heater air filter.
Damaged: R rear rain rail on OHG, battery OHG pull cover dents, R side cover mildly bent, L & R rear OHG lower side covers bent, R rear cab door seal, floorboard horn button cover, door mounted heater housing.
Needs Adj: Lift chains, tilt sync.

