

Direct Forklift and Equipment

7885 Southern Blvd, Boardman OH 44512

www.directforklift.com

330.726.4050

HN0024

Type of Equipment	Standard Forklift
Make	Hyundai

Model	70D-7A
Serial Number	HHKHfZ17VE0000024

Year	2014
Hours	2741



Capacity	15425
Tire Type	Pneumatic
Fuel	DIESEL
Hydraulic Controls	Hood
Hydraulic Functions	Four
Mast Height Lowered	118
Max Lift Height	157
Free Lift	No
Mast Stage	Two
Fork Length	46.5
Drive Tire Size	8.25-15
Steer Tire Size	8.25-15
Attachments	
Key Included?	Yes
Weight	22381
Unit Operating?	Yes

Fork Condition	Worn
Upright Condition	Good
Lift Cylinder Condition	Good
Hydraulics Condition	Good
Carriage Condition	Needs Attn
Drive Axle Condition	Good
Brakes Condition	Good
Parking Brake Condition	Needs Attn
Shift Action Condition	Good
Steer Axle Condition	Good
Sheet Metal Condition	Poor
Drive Tire Condition	Worn
Drive Tire Tread	40%
Steer Tire Condition	Worn
Steer Tire Tread	15%
Electrical System Condition	Good
Seat Condition	Torn
Lights Condition	Good
Engine Condition	Good
Cooling System Condition	Good

Engine Info	Kubota 3.8
-------------	------------

Shipping dimensions in inches (")

Length	139	Add fork length or attachment dimensions when applicable
Width	82	
Height	118	

HN0024

Comments

Engine oil low, clean; added 4.5 qts. Moist residue around oil drain plug.
 Wet oil residue bottom of bell housing.
 Trans fluid below low range, clean; none added.
 Wet oil residue on trans cooler and hose; dripping needs cleaned & further diag.
 Final drive oil was below dipstick, 1.5 gallons added; additional still needed to bring into range.
 Tilt cyl hoses & fittings @center junction dripping oil onto final drive.
 Moist oil res top L hyd tank & 3 fwd trans solenoids.
 Dry oil residue on fuel pump.
 Wet oily fuel res on sediment bowl & water sensor; one drop hanging.
 Hyd cab electric lift pump non operational; must manually raise cab, needs diag.
 Park brake cables & latch mech feel sloppy, may be damaged; needs attn. Park brake displays on dash as operating & disengages trans out of drive.
 Service brake pedals don't return when applied, must manually lift; brakes are operational.
 Debris wrapped/stuck in between dual wheels.
 3rd & 4th function hoses plugged @ lower mast.
 Unable to manually engage exhaust burn off procedure; may need further diag.
 Heavy scaly rust on both hyd tank assys; mild scaly rust on cab.
 Mild play in steer pins & bushings.
 Unit has no brake or BU lights.
 Mast rollers need cleaned & lube.

Missing: Both hood bonnet shocks, coolant res cap, ops manual, R brake pedal pad, (3) plastic dash switch plugs, attachment hoses/carriage brkts & junctions, metal fuse/ECM cover & hand bolt, battery hold down, top apron cross bar.
 Damaged: Floormat, both front fenders, L metal cab entry handle, seat adjusters sticky, seat rails seized, both front turn signal lens melted, carriage bent, mast tilt cyl pin lower housing plate bent, L bonnet cover, plastic display cover cracked, lower rear mast plate bent, R steer w/brg cover, R outer drive rim dent/bent, R steer wheel press ring, tilt & telescope column seized, tilt column rubber boot, L hyd tank storage door hinge seized, park brake cable outer sheath.
 Needs Adj: Lift chains.

