

Direct Forklift and Equipment

7885 Southern Blvd, Boardman OH 44512

www.directforklift.com

330.726.4050

TZ5696

Type of Equipment	Rail Car Mover
Make	Trackmobile

Model	5TMD	Year	
Serial Number	5696	Hours	1538



Capacity	
Tire Type	Pneumatic
Fuel	DIESEL
Drive Tire Size	8R 19.5
Steer Tire Size	8R 19.5
Attachments	
Key Included?	Yes
Weight	11000
Unit Operating?	Yes
Overall Rating	Fair
Overall Appearance	Fair
Engine Type	Detroit Diesel 5547-7040

Hydraulics Condition	Good
Drive Axle Condition	Good
Brakes Condition	Good
Parking Brake Condition	Good
Shift Action Condition	Good
Steer Axle Condition	Good
Sheet Metal Condition	Fair
Drive Tire Condition	Good
Drive Tire Tread	100%
Steer Tire Condition	Good
Steer Tire Tread	100%
Electrical System Condition	Needs Work
Seat Condition	Torn
Lights Condition	Good
Engine Condition	Good
Cooling System Condition	Good

Shipping dimensions in inches (")

Length	153	Add fork length or attachment dimensions when applicable
Width	100.5	
Height	100	

tz5696

Comments

Front lift wheel cyl rusted/pitted: leaking.

Rear drive wheel carriage raise/lower hyd cyl chrome ram rusted/pitted; no seeping or leaks.

Oily res on and around final drive yoke flange.

Clunky noise in train wheel drive line; needs further diag and possible lube.

Lower hyd hose leaking on coupler raise lower hyd cylinder under L cab. Park brake can be driven through in fwd; rev OK.

Heater switch on dash seized; unclear if heater fan is operational.

Unclear if sand boxes are operational; can hear relay click when buttons are pressed.

Water temp & converter temp gauges non op.

Amp meter non operational.

Strobe light & operator cab light non operational.

Track lights non operational.

Horn non op.

WS wiper non operational; needs diag.

Large lever to left of operator appears seized; unclear what function it operates.

Steer assys have some play in tie rods/bushings.

No power steering.

Air filter dirty; blown out date 10-12-04 @1492 hrs.

Missing: R side battery compartment cover, seat belt assy.

Damaged: Rad grill, metal front body cover, both metal str stop plates, L front & rear train wheel platforms dent/bent, R platform bent/dent, R rubber bumper worn/cracked, R air tank dent, hood dent/bent, R cab door mildly bent/dents, dash oil pressure gauge, front WS wiper blade worn, coupler release pull handle partially broken, hood cowl in front of WS rusted through, air box lid clamp/wing bolt & nut rusted, (1) broken screw front R upper king pin cover, lower front cowl insulation/sound mat, both front hood retainer clips, coupler height adj top chrome ram mild rust.

